

Mr. J. Hayne Roy Acting Director Space Management Division Office of Operating Program Public Buildings Service General Services Administration Washington, D. C. 20407

Dear Mr. Roy:

25X1C4a

25X1C4a 25X1C4a

Please refer to a letter dated 17 April 1973 from Hr. James W. McMahon, Acting Chief, Metro Operations, Space Management Division. General Services Administration, concerning deficiencies in the HVAC system of 1000 North Glebe Road, Arlington, Virginia

A recent survey of the HVAC system reveals that most of the deficiencies have been corrected and the systems are operating setisfactorily. It was discovered, however, that some of the air filters in the air handlers are improperly installed. It is requested that the Lessor be notified so that corrective action can be taken.

Sincerely,

25X1A9a

Acting Chief Real Estate and Construction Division, OL

Distribution:

Orig - Addressee

1 - OL/RECD Official

1 - OL/RECD/REB Chrono

1 - OL/RECD/RAFU

25X1A8a

- OL/RECD/HEB

D- Daily

1 - OL Reader

25X1A9a

OL/RECD/REB/I

:cmt/3438 (9 Jan 74)

WARNING NOTICE SENSITIVE INTELLIGENCE SOURCES

Approved For Release 2000/04/1

CLASSIFIED BY

EXEMPT FROM GENERAL DECLASSIFICATION SCHEDULT OF E () 11/92, I XEMPTION DATAGORY: § 58(1 , (2), (3) or (4) (circle one of more) AUTOMATICALLY DECLASSIFIED ON

RDP82-00803R000300190050-2

FROM:  REMARKS:  FROM:  ROOM NO.  BUILDING  ROOM NO.  BUILDING  BUILDING  RETENSION  ROOM NO.  BUILDING  ROOM NO.  R		TRANSM	IITTAL SLIP	Ē	
FROM:  ROOM NO. BUKDING EXTENSION	FOIAb3a	1116		1	
ROOM NO. BUILDING EXTENSION		REMARKS:			
ROOM NO. BUILDING EXTENSION					
ROOM NO. BUILDING EXTENSION					
ROOM NO. BUILDING EXTENSION					
ROOM NO. BUILDING EXTENSION					
ROOM NO. BUILDING EXTENSION		FROM:	04/8=	7.0	
			BUKDING		TENSION